




Schematic View of Stressing Losses






Release Jack



Force in tendon


Jacking stress 1

Seating losses 1





Right side jacking





Release Jack

